

Facilities & Construction Report


PROJECT STATUS 11/13/2017

Current Projects


- **New Construction**
 - Laughlin Campus
- **Energy Savings Initiative**
 - Audit Status
- **Campus Repairs**
 - Del Rio High School
- **Technology**
 - Service Desk Monthly Report

New Construction

Laughlin Base School



- Advertise for RFCP – Completed
- Receive RFCP – Completed
- Build Status – Completed
- Visual Inspection of Units – 11/08/2017
- General Contractor Awarding – 11/13/2017



New Construction

Laughlin Base School – Interior View



New Construction

Laughlin Base School – Interior View Continued



New Construction

Energy Savings Audit

- Water Audit (District Wide) – Compiled Data
- Lighting Audit (District Wide) – Compiled Data
- Engineering Design (District Wide) – Compiled Data
- Mechanical Audit (High School) – Compiled Data
- Building Automation (Applications) – 50% Completed
- Mid Term Review Expected – December 2017

Campus Repairs

Del Rio High School – Nurses Station



Campus Repairs


Del Rio High School – Cafeteria




Technology

Help Desk Support Tickets 10-1-2017 thru 11-1-2017


Tickets Submitted



Bar Chart - Count of Service Request by Location



Tickets Completed



Tickets Carried Over
178

The background is a dark blue gradient with a complex geometric pattern of thin, light blue lines and circles. The lines form a grid-like structure with various rectangular and circular shapes, some overlapping. The circles are of different sizes and are scattered across the frame, some partially cut off by the edges. The overall effect is a technical or architectural aesthetic.

Questions?